


PARTS (for Rejiband fitting)

Reinforced joint clamp




E.G.		E.B.		Pack unit
Ref.	/u	Ref.	/u	
64010061	0.027	64020061	0.026	50

H.D.G.		S.S. 316		Pack unit
Ref.	/u	Ref.	/u	
64030061	0.026	64060061	0.028	50

JUST 3 PARTS;

- Captive bolt
- Simplifies assembly
- 20% improvement in mechanical performance




Click connector



E.G.		E.B.		Pack unit
Ref.	/u	Ref.	/u	
64010020	0.072	64020030	0.072	25

- Quick fitting
- No bolts
- No special tools
- Electrical continuity guaranteed


Side joint-plate



E.G.		E.B.		Pack unit
Ref.	/u	Ref.	/u	
64010041	0.048	64020041	0.048	50

H.D.G.		S.S. 316		Pack unit
Ref.	/u	Ref.	/u	
64030041	0.05	64060041	0.048	50

Wire end cap



BLACK POLYETHYLENE		
Ref.	/u	Pack unit
68000049	0.001	100

Working temperature range: -50 °C / +60 °C


Material: Steel
Working temperature range: -50 °C / +150 °C

Weight in kilos

E.G. Electrogalvanised UNE - EN 12329
E.B. Bichromate Electrolytic zinc-plating UNE - EN 12329
H.D.G. Hot-dip galvanised UNE - EN-ISO 1461
S.S. 316 Passivated stainless steel AISI 316


Examples of assembly

CONNECTORS NEEDED EVERY 3 METERS




1 Wire end cap (page 22)



WIDE	
060	2
100	2
150	2
200	2+1
300	2+1
400	2+2
500	2+2
600	2+2




CONNECTORS NEEDED EVERY 3 METERS




1




WIDE	
100	2
150	2
200	2+1
300	2+1
400	2+2
500	2+2
600	2+2



2



4



3

